

Date: Thursday, 07/06/2007 10:52:36 AM  
User: Linda Lacelle

# Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: UPDATE PAPERW ECN964
Job Number	: 32844		
Estimate Number	: 10804		
P.O. Number	: <i>N/A</i>	Part Number	: Z_CUSTOM
This Issue	: 07/06/2007 S.O. No. : <i>N/A</i>	Drawing Number	: D350-607
Prsht Rev.	: NC	Project Number	: <i>N/A</i>
First Issue	: <i>N/A</i> Type : LARGE FAB ASSY	Drawing Revision	: <i>N/A</i>
Previous Run	: 00015	Material	: <i>N/A</i>
Written By	: <i>[Signature]</i>	Due Date	: 14/06/2007 Qty: 1 Um: Each
Checked & Approved By	: <i>[Signature]</i>		
Comment	:		

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1  
REMOVE FROM STK  
D350-607-041

*B31676*

D350-607-043

D350-607-045

D350-607-047-

*7/12/07*

ADD NEW PAPERWORK DSI 9273 REV.B

*[Signature]*

*[Signature]*

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1  
RETURN PARTS TO STK

*[Signature]*

*[Signature]*

3.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

*FD 07/06/08*

*(1)*

Job Completion



*W 07/06/08*